



Certificate of Registration

QUALITY MANAGEMENT SYSTEM - ISO 9001:2008

This is to certify that:

3M Fall Protection
3833 Sala Way
Red Wing
Minnesota
55066
USA

Holds Certificate No:

FM 534873

and operates a Quality Management System which complies with the requirements of ISO 9001:2008 for the following scope:

Design and manufacture of confined space entry/retrieval, fall-arrest equipment and engineered systems using aluminium and steel welding, machining, and assembly processes.

For and on behalf of BSI:



Carlos Pitanga, SVP, System Certification and Compliance

Original Registration Date: 2008-02-29

Latest Revision Date: 2017-05-17

Effective Date: 2017-01-18

Expiry Date: 2018-09-14

Page: 1 of 2



...making excellence a habit.™

Certificate No: **FM 534873**

Location

3M Fall Protection
3833 Sala Way
Red Wing
Minnesota
55066
USA

Capital Safety Group Canada Ltd.
260 Export Boulevard
Mississauga
Ontario
L5S 1Y9
Canada

Registered Activities

Design and manufacture of confined space entry/retrieval, fall-arrest equipment and engineered systems using aluminium and steel welding, machining, and assembly processes.

Design and manufacture of confined space entry/retrieval, fall-arrest equipment and engineered systems using aluminium and steel welding, machining, and assembly processes.



Original Registration Date: 2008-02-29

Latest Revision Date: 2017-05-17

Effective Date: 2017-01-18

Expiry Date: 2018-09-14

Page: 2 of 2